

56 addressable registers of width 24 - 8064

24 * Resource Usage Report

jkff - 144

108 * add_fx_6_18 - 67392

16 * adc_fx_6_18 - 9984

6 * sub_fx_6_18 - 3744

2 * sbc_fx_6_18 - 1248

Total Cost 90576